

SPERRY MARINE UK
Service Bulletin No. 46

Product: Decca FishMaster FS series Colour Video Plotter

Subject: General Information 1

Spares Parts List

From around the middle of June '03 the following Spare Parts will be available for the Decca FishMaster FS series CVP.

Description	Part Number
Floppy Drive	88NT02
Hard Drive	24AD22
PSU	70EM23
Fan	03LM03
Air Filter	81EG02

Processor Unit

- It has been discovered that the 4 way in line connector feeding the power to the Hard Disk is of poor quality and causes intermittent HD failure.
- It has also been discovered that the Dongle interface cable can be reversed (when supplied as an exchange unit) as it is not tested with a Dongle.
- The supplier of the Processor Unit has stated that when returned Processor Units have been tested for repair, often they have found software Viruses on the system. It is important that all customers are made aware that they should ensure that only virus free disks must be used in their system.